Maryland Historical Trust

Maryland Inventory of Historic Properties number:	AL-II-A-329.
The bridge referenced herein was inventoried by the leading to the leading of the leading to the	Maryland State Highway Administration as part of the list with eligibility determinations in February 2001. April 3, 2001. The bridge received the following
	STORICAL TRUST Eligibility Not Recommended X
Eligibility Recommended	
Eligibility Recommended	Eligibility Not RecommendedX
Eligibility Recommended Criteria:ABCD Consideration	Eligibility Not RecommendedX
Eligibility Recommended Criteria:ABCD Consideration	Eligibility Not RecommendedX

Jugan

Maryland Inventory of Historic Properties Historic Bridge Inventory Maryland State Highway Administration Maryland Historical Trust

MHT Number AL-VI-A-329

Name and SHA No. MD 636 over Warrior Run/1072 (1017210)

<u>Location:</u> Street/Road Name and Number: <u>MD 636</u>
City/Town: Cresaptown Vicinity_
County: Allegany
Ownership: x State County Municipal Other
This bridge projects over: _Road_Railwayx Water_Land
Is the bridge located within a designated district: yes x no
_NR listed district_NR determined eligible district _locally designated_other Name of District
Bridge Type:
_Timber Bridge _Beam Bridge_Truss-Covered_Trestle _Timber-and-Concrete
_Stone Arch
_Metal Truss
_Movable BridgeSwingBascule Single Leaf_Bascule Multiple LeafVertical LiftRetractilePontoon
<u>x</u> Metal Girder <u>x</u> Rolled GirderRolled Girder Concrete Encased Plate GirderPlate Girder Concrete Encased

_Metal Suspension
_Metal Arch
_Metal Cantilever
_Concrete _Concrete Arch _Concrete Slab_Concrete Beam _Rigid Frame _Other Type Name
Description:
Describe Setting: Bridge 1072 (1017210) carries MD 636 over Warrior Run in Allegany County Maryland. MD 636 runs generally north-south at this location; Warrior Run flows east-west. The bridge is located in a small town setting with early 20th century structures in view.
Describe Superstructure and Substructure: The superstructure is a single span steel beam bridge with a concrete deck and bituminous wearing surface, and W-beam guardrails. The span length and total bridge length is 24'. The substructure is reinforced concrete abutments and wing walls.
Discuss Major Alterations: There is no indication in the SHA bridge files that major alterations have ever been made to this structure. However, it is unlikely that there have been no repairs. It is possible that no major alterations have occurred, but it is highly probable that minor repairs such as cleaning, painting or filling in of cracks and spalled areas have occurred routinely. The files for this bridge are not complete, so there is no way of confirming these probabilities.
<u>History:</u>
When Built:1936 Why Built:local transportation needs Who Built:State Roads Commission Why Altered:n/a Was this bridge built as part of an organized bridge building campaign:yes
Surveyor Analysis:
This bridge may have NR significance for association with: _A Events _Person _C Engineering/Architectural

Was this bridge constructed in response to significant events in Maryland or local history:no

AL-VI-A-329

When the bridge was built and/or given a major alteration, did it have a significant impact on the growth and development of the area:no

Is the bridge located in an area which may be eligible for historic designation and would the bridge add to or detract from historic and visual character of the possible district:no

Is the bridge a significant example of its type:no

Does the bridge retain integrity of the important elements described in the Context Addendum: Because no major alterations have been made to the structure it is likely that it retains its integrity.

Is the bridge a significant example of the work of the manufacturer, designer, and/or engineer and why:no

Should this bridge be given further study before significance analysis is made and why: Further study is not warranted for bridge 1072 (1017210). Even though it retains its integrity, it is not a significant example of its type.

Bibliography:

Greiner, Inc.

1995 Historic Bridge Inventory Form

Spero, P.A.C. & Company, and Louis Berger & Associates

1994 Historic Bridges in Maryland: Historic Bridge Context

United States Geological Survey

1949, 7.5' Cresaptown Quadrangle, photorevised 1974

State Highway Administration


v.d. Bridge Inspection Files

Surveyor:

Name: Stephanie L. Bandy Date: September 1995

Organization: State Highway Admin. Telephone: (410) 321-2213

Address: 2323 West Joppa Road Brooklandville, MD 21022





AL-II-A-329

BR # 1017210 (1072)

WARRIOR RUN

ALLEGANY CO., MD

DAYID KING

1/27/95

SHA

WEST ELEVATION



AL-II-A-329

BR #1017210 (1072)

WARRIOR RUN

ALLEGANY CO, MD

DAVID P KING

1/27/95

SHA

EAST ELEVATION

2 OF 4



AL-II-A-329

BR # 1017210 (1072)

WARRIOR RUN

ALLEGANY (O, MD)

DAVID P KING

1/27/45

SHA

SOUTH ELEVATION (POWNSTREAM)

3 OF 4



AL-VI-A-329 BR# 1017210 (1072)
WARPINE RUN
ALLEGANY CO, MD
DAVID P. KING
1/27/95
SHA

NORTH ELEVATION (UPSTREAM)

4 OF 4